

The diagram illustrates a 3-phase electrical distribution system. At the top, the main supply (Einspeisung) is connected to a 63A fuse. The supply lines are labeled L1, L2, L3, N, and PE. The system is divided into five stations, each with its own set of fuses (2F1-2F5) and a terminal block (X100-X110). The stations are labeled as follows:

- Station 3:** Werner Palettierer AS Flansch einlegen
- Station 4:** Simmerring fetten und einpressen
- Station 8:** Sabiel Palettierer 1 Rotor einlegen
- Station 8:** Rotor in BS Flansch einpressen
- Station 10:** Sabiel Palettierer 2 Stator einlegen

The diagram also shows a main switch (1Q1_2) and a main terminal block (XL1, XL2). The PE line is connected to a ground symbol with the text "An allen Anschlußstellen nach VDE 0113".

1				2		3		4		5		6		7		8		9		0	
				Datum	06.03.01	GEORG WESTPHAL GMBH Celle		Wilhelm-Hasselmann-Str. 27B D-29227 Celle Tel.: 05141/9551-0		GEFEG Hannover Motorlinie		230/400V AC Versorgung				-		+			
				Bearb.	E.Schirr.																
				gepr.																	
Zustand	Änderung	Datum	Name	Norm		Ursprung	Ers. f.		Ers.d.			Z.-Nr.		M37027				Seite 2 von 4			

[illegible]

Station 5+6
Kabelanlöten

Station 11
Stator wenden und AS Flansch aufdrücken

Station 12
Motor verschrauben

Station 14+15
Encodermontage

Station 16
Motor einlaufen

Station 20+21
Schlechtteile und Verpackung

1		2		3		4		5		6		7		8		9		0	
Datum		03.03.01		GEORG WESTPHAL GMBH		Wilhelm-Hasselmann-Str. 27B		D-29227 Celle		GEFEG Hannover		230/400V AC Versorgung		-		Z.Nr.		Seite 4	
Bearb.		E.Schirr.		Celle		D-29227 Celle		Tel.: 05141/9551-0		Motorlinie				+		M37027		von 4	
gepr.				Ursprung		Ers. f.		Ers.d.											
Zustand		Änderung		Datum		Name		Norm											